



Central portion of Coyote Creek Drainage  
Diverted along northern site boundary.

Eastern portion of Coyote Creek Drainage.



View generally southwest. Grove area is on the eastern portion of the site.  
Photograph 1



Drainage channel immediately north of northeast corner of site.  
Photograph 3



View of granular sediments exposed in five-foot  
vertical cut in channel northeast portion of site.  
Photograph 4

View facing east of active wash north of soil berm along northern site boundary.  
Photograph 2